


July 22, 1994

At 11:30 am Don Robertson reported to me that a discharge was noticed originating at the Somitex property and flowing into the drainage channel.

I observed minor flowing liquid originating from the West side (nearest the Corporate office) of the Somitex building near the point where the south end of the Somitex employee parking lot intersects their building. The flow was nearly due west across the employee parking lot and then proceeded north when it reached the easement. Noticed inside the employee parking lot, at the fence line between the employee parking lot and the easement, were four discarded Castrol oil containers. These containers were in the middle of the discharge flow.

The easement area just south of the Utility property line consists of a low area with a small amount of dirt and vegetation. This area displayed an area of wet soil that extended approximately 4 feet on either side of the centerline of the easement. This suggested that the discharge had a significant initial flow and that I was witnessing the latter stages of the flow. The discharge extended to the southern boundary of the Utility site.

Tony Esnault was informed by me of the discharge and attempted to take photographs of the flow; however, his camera did not function properly. I asked him to log the discharge in his stormwater plan report and attempt to take pictures after lunch if he can repair his camera.



Robert Griffis

UTM 005033



Utility International
Aftermarket Parts Division


Sales Support • Technical Support
800 929-4631 800 423-6515

On Friday Feb 4, 1994 at Apex.
12:30 pm I Robert Ojeda saw water
running down the driveway at Somatex
Co. The water had a light green color to
it, and was entering the property of
Utility Trailer. Walking along the
fence I could see a light green residue
that was being left behind on the
driveway. A sample of water was
taken from the water entering the
property of Utility Trailer.

Robert Ojeda

FEB 7, 1994

ON FEB 4 AT APROX 12:30 PM. I
NOTICED IN THE RUN OFF WATER
A GREEN SUBSTANCE. I FOLLOWED IT
TO THE SOUTH END OF OUR PLANT.
THE WATER WITH GREEN IN IT WAS
COMING FROM THE DRIVEWAY OF
THE PLANT TO THE SOUTH ALONG
THE CURB. FOLLOWED IT TO THE
EAST AND IT WAS COMING FROM
THE SOUTH EAST SIDE OF THE
PLANT TO THE SOUTH OF OURS.



(Weather: ~80°F
warm, clear w/ high clouds)

3-16-94
1400hrs

I observed a discharge of liquid coming from the west side of the Somitex building (sourced near the point where the fence between the parking lot and the unpaved area intersects the building - about $\frac{1}{3}$ of the way south of the north west corner of building). This discharge travelled across their employee parking lot, into the drainage channel on the right-of-way and into Utility's subgrade drainage channel. Color was not detectable, but there was an unrecognizable odor; quantity discharged seemed to be 150 to 200 gallons. There was not a sufficient amount in the Utility drainage channel to collect a sample for analysis.

Informed John Stanton of situation and sat in during his phone call to David Ayers at Somitex to inform him of discharge. Called Tony Esnault and watched as he took photographs of discharge.

Robert M. H.

UTILITY TRAILER ENVIRONMENTAL ENGINEER
CA REGISTERED ENVIRONMENTAL ASSESSOR REA-03409

UTM 005036

Fri Feb 4, 1994

On this date at about 10:00 A.M. I observed rain run off water entering the concrete lined drainage ditch at the southwest fence line of our property.

This run off water was very green in color as if it were contaminated.

I observed the same thing about 1:00 P.M. although the flow was greatly reduced.

Grant B. Barton