CHEMICAL CONSULTANTS

1160 CENTRE DRIVE
INDUSTRY, CALIFORNIA 91789
(714) 596-7473 — (818) 966-7122

Sanitex Discharge

A REPORT PREPARED FOR:

UTILITY TRAILER
17300 East Chestnut
Industry, CA 91748

DATE: July 27, 1988
RECEIVED: 07/18/88
CUSTOMER P.O.: C-002865
LOB NUMBER: LW-6381

TYPE MATERIAL TESTED: (1) Grab sample labeled 2-SW taken on 07/17/88 provided by customer.

REASON FOR TEST: Determine concentration of constituents listed below for customer's information.

RESULTS

METHYLENE CHLORIDE	ND <10	ppb
CHLOROFORM	7	ppb
CHLOROETHANE	ND <10	ppb
CARBON TETRACHLORIDE	ND < 5	ppb
BROMOFORM	ND < 5	ppb
1,2-DICHLOROETHANE	ND <10	ppb
TRICHLOROETHYLENE	ND < 5	ppb
1,1,1-TRICHLOROETHANE	ND < 5	ppb
1,1-DICHLOROETHANE	ND <10	ppb
1,1,2-TRICHLOROETHANE	ND <10	ppb
1,1,2,2-TETRACHLOROETHANE	ND < 5	ppb
2,CHLOROETHYL VINYL ETHER	ND <50	ppb
t-1,2-DICHLOROETHENE	ND <50	ppb
1,2-DICHLOROPROPANE	ND <50	ppb
1,3-DICHLOROPROPENE c&t	ND < 5	ppb
CHLORODIBROMOMETHANE	(trace)< 5	ppb
BROMODICHLOROMETHANE	(trace)< 5	ppb
TRICHLOROFLUOROMETHANE	ND < 5	ppb
TETRACHLOROETHYLENE	ND < 5	ppb
CHLOROBENZENE	ND <20	ppb
1,2-DICHLOROBENZENE	ND <10	ppb
1,3-DICHLOROBENZENE	ND <10	ppb
1,4-DICHLOROBENZENE	ND <10	ppb

TEST METHOD: Halogenated Volatile Organics---- EPA 8010, Method 3810, ECD Detector.

Respectfully submitted,

Chemical Consultants