CPP
SECURITY SERVICE

INCIDENT REPORT

Corporate Offices. 6727 Odessa Ave., Van Nuys, CA 91406

CALIFORNIA PLANT PROTECTION INC.

CLIENT: UTility Trailers LOCATION: Gate by Corperate OFFice

DATE OF INCIDENT: 7-17-88 TIME OF INCIDENT: 09:11

DESCRIPTION OF INCIDENT:

(Explain in detail. Consult instruction sheet for check list.)

While on detex patrol, I Noticed that there was run OFF water from Samitex, So I completed my patrol and came back to guard shack to get sample bottle. I then returned to where I saw water And took A sample OF it. The Area where water was, is drainage by Corperate, or left OF Corp.

ACTION TAKEN:

(Who investigated? Who was notified? Was situation corrected?)

Took sample

COMMENTS AND RECOMMENDATIONS:

(Should further action be taken? Can future incidents of this nature be prevented? How?)

We need more sample containers

REPORTING OFFICER'S SIGNATURE Myron Lewis BADGE NO. Cpl-1048

SUPERVISOR'S SIGNATURE _____ DATE _____

NOTE: COMPLETE IN DUPLICATE. (ORIGINAL TO CLIENT, COPY TO SUPERVISOR)

"WE TAKE PRIDE"